



# ABS Sensor Service Kit

## Meritor Style ABS Sensors

Part No.	Description	Harness Length	Replaces Meritor Wabco
GTA-R955349	Straight	2 ft	R955349
GTA-R955329	Straight	5.6 ft	R955329
GTA-R955337	Straight	5.8 ft	R955337
GTA-R955335	90 degree	1 ft	R955335
GTA-R955336	90 degree	3 ft	R955336
GTA-R955365	90 degree	4.6 ft	R955365
GTA-R955341	90 degree	5.8 ft	R955341
GTA-R955342	90 degree	6.6 ft	R955342



## Bendix Style ABS Sensors

Part No.	Description	Connector Type	Harness Length	Replaces Bendix
GTA-801544	90 degree	DIN	1 ft	801544
GTA-801545	90 degree	Deutsch	8.6 ft	801545
GTA-801546	90 degree	Deutsch	5 ft	801546



## ABS Sensor Clip

Part No.	Length	I.D.	O.D.	Replaces Tectran
GTA-8997598154	1.18"	.63"	.71"	S899-759-815-4

Air Brakes